


Figure 1



Existing Alder Lap Pool Liner
- glued seams and lane tiles
lifting

Figure 2



Pool basin floor detached from drains

Figure 3



Ceramic tiles
detaching from
liner, in
numerous
locations
continuously

Figure 4




Polished Stainless Steel Lap Pool with Ramp

Figure 5



Polished Stainless Steel Leisure Pool - curved walls

Figure 6



Polished Stainless Steel Lap Pool Under Construction in Town of Oakville 2020

Figure 7



Polished Stainless Steel - Mechanical/Filtration Room (1/3 size of traditional pool mechanical room)

Figure 8



Oakville Stainless Steel Construction