

87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

Option 2 – no sidewalk. (Leave as is.)

M Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by **4:00 P.M. on Wednesday March 24th, 2021.**

Yours truly,

Duros

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway



Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



0 37.5 75 150 Meters

The Safety of the residents and students from O.D.S.S. and Princess Elizabeth School should be the primary concern,

the amount of kends and changes in elevation on kends (on Sunset especially) are dangerous when walking on the road. Especially in the winter when there are snowbanks.

I don't like the idea of pedestrians crossing the street on the bend at Northgate and Forest Park to access the walkung.

I would rather see plople cross from the west side of Sunset to the east side of Sunset and then be on the same side as the Walkway between Northgate and Bredin Parkway. Plus that would make the large green electrical box on the west side of Sunset a non issue. (obsticle) Shown in red. I think there should also be a sidewalk from the walkway at the back of O.D.S.S. to the Walkway between Northgate and Brodin Parkway. Attn. Infrastructure Services

In regards to the proposed construction of a sidewalk from the high school to the existing walkway on Northgate Drive on the north and west side of Sunset Drive we choose option 2 - leave as is.

We have lived at this address (right next to the aforementioned walkway) for fourteen years. All four of our children attended ODSS.

There is a clear and unobstructed view out our front door and directly up Forest Park Road. Every morning, lunch hour and after school for the past fourteen years I have watched the students come down the street by way of the walkway from the high school onto Glenforest Road and then down Forest Park Road. On any given day there are less than two or three students and/or pedestrians taking the route mentioned in your report. The lack of foot traffic in the mentioned area has nothing to do with the absence of a sidewalk and everything to do with the grade and the distance between the high school and the walkway at Northgate. Human nature dictates taking the shortest and most level route between point A and point B. The route described in your report is neither of these.

Thank you for considering our opinions.

Sincerely,

Jeffrey and Cynthia Cotton 5 Northgate Drive <u>Sent from Rogers Yahoo Mail for iPad</u> Attn. T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Re: Report No. INS-2020-013

Falkner (Faulkner) Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk

OPTION 2 - no sidewalk. (Leave as is.)

Comments:

My husband and I moved onto Sunset Drive in 1975 when our children were 5, 8 and 12. A number of young families lived on Sunset Drive at that time and thereafter, and, to my knowledge, there were no accidents or near accidents when the children were walking to and from school. Since there is no through traffic in any direction from Sunset Drive, Northgate, Forest Park and Glenforest, there is very little traffic at any given time except for those living on the above named streets.

Also, there is a minimal amount of foot traffic by students or other pedestrians. Students tend to use the crosswalk from the parking lot at the north side of ODSS to Glenforest, to Forest Park and then to the Bredin Parkway walkway. If students do use Sunset Drive, I have noticed that they tend to turn east at the corner of Sunset and Sunset and then go north to Bredin Parkway walkway. But, as mentioned above, there is very little foot traffic by students.

If anything should be addressed, it is the precarious area at the bend in the road when Faulkner Street turns into Sunset Drive.

Sincerely,

Dorothy Donnelly 12 Sunset Drive



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

- Option 1 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;
 - Option 2 no sidewalk. (Leave as is.)

Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by **4:00 P.M. on Wednesday March 24th**, **2021**.

Yours truly,

D. Duoso

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

From:Julie RawnTo:Julie RawnSubject:Re: Sunset Dr sidewalk poll.pdfDate:Tuesday, March 23, 2021 11:59:04 AM

Hi Julie, My address is:

Alan Tate 33 Sunset Dr Orangeville ON L9W 2H1 Canada

Regards, Alan

On Tue., Mar. 23, 2021, 11:56 a.m. Julie Rawn, <<u>jrawn@orangeville.ca</u>> wrote:

Thank you Alan, can you please provide your address?

Julie

Ext. 2289

From: Alan Tate Sent: Tuesday, March 23, 2021 11:55 AM To: publicworksinfo <<u>publicworksinfo@orangeville.ca</u>> Subject: Sunset Dr sidewalk poll.pdf

Hello,

My completed copy of the poll about the proposed sidewalk on Sunset Drive is attached.

I voted no because the scope of the project is much larger than was originally presented to me and too many trees would need to be removed.

Regards,

Alan

Attn. T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Re: Report No. INS-2020-013

Falkner (Faulkner) Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk

OPTION 2 - no sidewalk. (Leave as is.)

Comments:

My husband and I moved onto Sunset Drive in 1975 when our children were 5, 8 and 12. A number of young families lived on Sunset Drive at that time and thereafter, and, to my knowledge, there were no accidents or near accidents when the children were walking to and from school. Since there is no through traffic in any direction from Sunset Drive, Northgate, Forest Park and Glenforest, there is very little traffic at any given time except for those living on the above named streets.

Also, there is a minimal amount of foot traffic by students or other pedestrians. Students tend to use the crosswalk from the parking lot at the north side of ODSS to Glenforest, to Forest Park and then to the Bredin Parkway walkway. If students do use Sunset Drive, I have noticed that they tend to turn east at the corner of Sunset and Sunset and then go north to Bredin Parkway walkway. But, as mentioned above, there is very little foot traffic by students.

If anything should be addressed, it is the precarious area at the bend in the road when Faulkner Street turns into Sunset Drive.

Sincerely,

Dorothy Donnelly 12 Sunset Drive



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the . COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

- □ Option 1 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;
- Option 2 no sidewalk. (Leave as is.)

Additional Comments: Suparate sheet

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly,

D. Durost


T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



N



Additional Comments . Why such a wide sidewalk ? 1. I do not want my two drevenage choqued up. 2. I don't want snow 't salt pushed up. any further 3. one my front lawon If you use the plow on the sidewalk in the winter I don't want to have to slean up after 2 snow plows 4. 5. Lids can wall through the back lane to flen Forestikway which would be a lot safes woute to Bithget & Breden Parkway If people would stop parking in the NO PARKING ZONE 6. at the school the kids would have more room to walk. If you want to put a sidewalk on Sylva Bradley's property 7. OKAY but not on my property.

M. RENNICE 19 SUNSET DR.





87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

- □ Option 1 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;
- Option 2 no sidewalk. (Leave as is.)
- Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly,

D. Duras

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed - Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



0 37.5 75 150 Meters



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303 Kenneth & Nancy Fockler 15 Sunset Dr Orangeville ON L9W 2G8

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- . mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

□ Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

Option 2 – no sidewalk. (Leave as is.)

Additional Comments: YES IT'S VERY DANGEROUS. DRDLY NEEDED AS SHOWNLIN RED ON ATTACHED HAF, BUT NOT

Thank you for taking the time to complete this brief questionnaire and survey. Please return your NEEDED OR WHATED BEYOND THATS survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly.

). Duras

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

Factoren

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk




N

150 Meters 37.5 75 0

. 1

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



0 37.5 75 150 Meters



Infrastructure Services:

The following is my response to the March 9th letter that was distributed for comment by residents:

The original petition submitted by Sylvia Bradley was prompted by the lack of by-law enforcement in one particular location, along the her property in what I will refer to as the Sbend. Despite the existence of No Parking and No Stopping signage, there have been many instances where illegal parking has been observed. Repeated attempts by residents to bring this matter to the attention of town staff have resulted in little to no response to date. Even meetings with a vice-principal of ODSS to encourage use of parking on the schools west side have resulted in limited success. Since the roadway is beyond the schools control, it is the municipalities responsibility to enforce posted parking restrictions.

The point inferring that students going from Bredin Parkway and Northgate to ODSS need a sidewalk on Sunset Drive is a non-issue. Due to the changes in grade or elevation on Sunset, the preferred choice of route by students is west on Forest Park and south on Glenforest to the walkway into the school. This has shown to be beneficial even for those students going up to Princess Elizabeth public school.

My family home was built back in around 1958, which is over sixty years ago and there has never been the need or any requirement for a sidewalk and there isn't one now. The majority of residents in this area purchased homes knowing full well that there weren't any sidewalks and for many it was a factor in their decision to buy. When Sunset Drive was being reconstructed, the residents were asked if they wanted sidewalks and the majority response was negative. Over the years I have had a number of discussions with residents about many local issues and can assure you that when asked about sidewalks, the response was always the same. The most recent emphatic response by a home owner was that a sidewalk would prompt him to sell.

Navigating Sunset Drive is enough of a challenge during the winter months, without having to maintain an unnecessary strip of pavement. May I also forward a residents suggestion that instead of spending tax dollars on a sidewalk that will undoubtedly get little to no use while creating an ongoing expense to maintain, it would be beneficial to allocate those funds to traffic lights at the Fead and First street intersection. The last petition that included residents signatures from Glenforest, Forest Park, Sunset, Faulkner, Mathew, Fead, McCarthy and First streets indicated significant support for Traffic Lights with a Pedestrian Crosswalk at this

heavily accessed intersection. Now, this is an area that really gets a large amount of vehicle and pedestrian traffic and safety is an ongoing concern.

Should my option regarding the subject matter be lost in the comments above; I definitely <u>do</u> <u>not</u> want to see a concrete sidewalk as being proposed on Sunset Drive, therefore select Option 2- no sidewalk (Leave as is)

Sincerely,

Alan Toms 10 Sunset Drive

From:	
То:	Tony Dulisse
Cc:	Julie Rawn
Subject:	Re: Faulkner Street-Sunset Drive Sidewalk Location Plan
Date:	Thursday, March 18, 2021 12:54:53 PM

Hi Tony,

Our address is 31 Sunset Drive.

Cheers Jeff

From: Tony Dulisse <tdulisse@orangeville.ca> Sent: March 18, 2021 11:40 AM

To:

Cc: Julie Rawn <jrawn@orangeville.ca> **Subject:** RE: Faulkner Street-Sunset Drive Sidewalk Location Plan

Hi Jeff. Thank you for your response. Could you provide your address for the file.

Thanks,

Tony Dulisse, CET |Engineering Technologist|Infrastructure Services

Office Number- 519-941-0440 Ext. 2248 | Toll Free 1-866-941-0440 Ext. 2248 | Cell: 519-942-6885 Connect with the Town of Orangeville online!

From: Julie Rawn <jrawn@orangeville.ca>
Sent: March 18, 2021 11:07 AM
To: Tony Dulisse <tdulisse@orangeville.ca>
Subject: FW: Faulkner Street-Sunset Drive Sidewalk Location Plan

Julie Ext. 2289

From: Jeff Bolton
Sent: Thursday, March 18, 2021 10:31 AM
To: publicworksinfo <<u>publicworksinfo@orangeville.ca</u>>
Subject: Faulkner Street-Sunset Drive Sidewalk Location Plan

Please find enclosed our survey response.

We have selected Option 2 - No Sidewalk (Leave As Is).

Cheers

Jeff



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at <u>publicworksinfo@orangeville.ca</u>; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

Option 2 – no sidewalk. (Leave as is.)

Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly,

). Durose

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

We are STRONGLY opposed to the proposed sidewalk on Sunset Drive/Northgate and we vote Option 2 "LEAVE AS IS".

Thank you.

Sincerely

Elizabeth Bolton 31 Sunset Drive Orangeville ON



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303



Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

John Overland

9 Sunset Dr Orangeville ON L9W 2G8

10

Plowed In

the winter

- Option 2 no sidewalk. (Leave as is.)
- Additional Comments: Where is the Snow going

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly,

D. Duroas

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed - Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



N

0	37.5	75	150 Meters
1	1 1 1		



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Own of Changevil

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

27 SUNSET Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from CDSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

□ Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

Option 2 - no sidewalk. (Leave as is.)

Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.


Yours truly,

V. Duros

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



0	37.5	75	150 Meters
	1 1 1		



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

K Option 2 – no sidewalk. (Leave as is.)

Additional Comments:

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.

Yours truly,

). Durost

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed - Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk



N

0 37.5 75 150 Meters



87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at <u>publicworksinfo@orangeville.ca</u>; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

Option 2 – no sidewalk. (Leave as is.)

MAdditional Comments: please see the attachment.

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by **4:00 P.M. on Wednesday March 24th, 2021.**

Yours truly,

). Duroze

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed – Falkner Street-Sunset Drive Sidewalk Location Plan

From:	
To:	publicworksinfo
Cc:	
Subject:	Report number INS-2020-013
Date:	Monday, March 15, 2021 9:58:11 AM
Attachments:	S22DIVM0321031508100.pdf

With regards to the proposed construction of a side walk that runs from ODSS to the existing walkway between Bredin Parkway and Northgate Drive, I would like to add a few comments along with the attachment.

Sunset Drive is the only **entrance and exit** that goes into the subdivision that includes Northgate Dr, Forest Park Rd, Glenforest Rd, therefore a very busy street with close to 100 homes.

My husband and I witnessed an elderly lady who has Alzheimer's fall on the road due to a speeding car outside our house, her and her son were trying to avoid the car. A side walk would definitely prevent this from happening again.

We see numerous elderly people and young families walking on our busy street with children, dogs and strollers; a side walk is desperately needed.

Sunset Drive is the only street for the high school students walking from Bredin Parkway to ODSS and for that reason the pedestrian traffic is quite busy during the school year.

For the above reasons I firmly believe that a side walk is a necessity for safety reasons.

Thank you for your consideration.

Paula Fogt 53 Sunset Drive Orangeville, Ontario L9W 2H1

CONFIDENTIALITY NOTICE This e-mail

transmission contains privileged and/or confidential information and the sender does not waive any related rights and obligations. The information is intended only for the use of the individual or entity named above. Any distribution, use or copying of this e-mail and any attachments or the information it contains by other than an intended recipient is unauthorized. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or the taking of any action in reliance on or regarding the contents of the e-mail information is strictly prohibited. If you have received the e-mail in error, please notify the sender (by return e-mail or otherwise) immediately and delete all copies of the email together with any attachments. Peel Regional Police

____.__

From:	
То:	publicworksinfo
Cc:	
Subject:	Proposed construction of sidewalk Report # INS-2020-013
Date:	Saturday, March 13, 2021 4:49:06 PM

Good afternoon,

We are writing to advise you we are NOT in favour of the proposed sidewalk for the reasons listed below;

- We have NOT witnessed or heard of any pedestrian safety issues in the area (in our 20 years living and raising children here).
- We find the timing odd given the Town's unmarked speed limit was just reduced, which will only add an element of increased safety to an already safe situation.
- The majority of foot traffic to and from Bredin Parwkway is along Forest Park, NOT Sunset Drive.
- A hydro box would need to be moved and there does NOT appear to be sufficient space for a sidewalk from a snow plowing perspective.
- There are far greater safety risks for both student foot traffic and citizens (pedestrians and vehicle occupants) at the Fead and First Street intersection, where a traffic light should be prioritized (especially now, given current proposed town house development on First Street).

To be honest, we are surprised investing in a sidewalk in the area is under objective consideration by the Town and wonder what supporting data backs the proposal?

In sum, we are strongly in favour of "LEAVING AS IS" and putting any available funds towards a traffic light at Fead Street and First Street for the future safety of FAR MORE students and citizens of Orangeville.

Sincerely, Carolyn Brown and Ed Johnston 1 Northgate Drive Orangeville, ON L9W 2H2 Sent from my iPhone

From:	
То:	Tony Dulisse
Cc:	Julie Rawn
Subject:	RE: Falkner Street - Sunset Drive 1.8 metre Curb Facing Proposed Sidewalk - NO SIDEWALK
Date:	Thursday, March 11, 2021 10:41:50 AM
Attachments:	image001.png

No problem Tony,

25 Sunset Drive.

We just moved in last year (May 19, 2020) and one of the selling points to the property for my wife and I was the fact it had no sidewalk in front.

So as clearly marked on my scanned form, we are strongly against the construction of a sidewalk anywhere on our property.

Thank you very much for receiving the questionnaire Mike (and Heather)

Thanks,

Mike Talotti ISPA Store Fixtures T: 905.702.2727 Ext. 7104 | C: 647.268.8339 | F: 905.702.2773 www.ispagroup.com



From: Tony Dulisse <tdulisse@orangeville.ca>
Sent: Thursday, March 11, 2021 10:26 AM
To: Mike Talotti
Cc: Julie Rawn <jrawn@orangeville.ca>
Subject: FW: Falkner Street - Sunset Drive 1.8 metre Curb Facing Proposed Sidewalk - NO SIDEWALK

Hi Mike. thank you for responding. Could you please provide your address.

Thank you.

Tony Dulisse, CET |Engineering Technologist|Infrastructure Services

Office Number- 519-941-0440 Ext. 2248 | Toll Free 1-866-941-0440 Ext. 2248 | Cell: 519-942-6885 Connect with the Town of Orangeville online!

From: Julie Rawn <jrawn@orangeville.ca</pre>

Sent: March 11, 2021 9:18 AM

To: Tony Dulisse <<u>tdulisse@orangeville.ca</u>>

Subject: FW: Falkner Street - Sunset Drive 1.8 metre Curb Facing Proposed Sidewalk - NO SIDEWALK

Julie Ext. 2289

From: Mike Talotti <

Sent: Thursday, March 11, 2021 9:14 AM

To: publicworksinfo < publicworksinfo@orangeville.ca>

Cc: Heather Soules

Subject: Falkner Street - Sunset Drive 1.8 metre Curb Facing Proposed Sidewalk - NO SIDEWALK

Please confirm with a response that you have received this email (with attachment that checks Option 2 – NO SIDEWALK (Leave as is))

Thank you very much, Mike

Thanks,

Mike Talotti ISPA Store Fixtures T: 905.702.2727 Ext. 7104 | C: 647.268.8339 | F: 905.702.2773 www.ispagroup.com





87 Broadway, Orangeville, ON L9W 1K1 Tel: 519-941-0440 Fax: 519-941-5303

Toll Free: 1-866-941-0440

Infrastructure Services

March 9th, 2021

Dear Resident:

In December 2020, Council directed Infrastructure Services to seek comments from residents regarding the proposed construction of a 1.8-metre-wide curb face sidewalk. The sidewalk being proposed runs from ODSS high school to the existing walkway between Bredin Parkway and Northgate Drive on the north and west side of Sunset Drive. Please refer to attached plan showing the proposed sidewalk location.

We would kindly ask you to complete and return the following brief survey. Responses can be:

- e-mailed to Public Works at publicworksinfo@orangeville.ca; or
- mailed or dropped off at 87 Broadway. Note: Town Hall is currently closed due to the COVID pandemic. Dropped off surveys/comments can be placed in the drop box next to the Town Hall Second Street entrance.

As background, Council was asked to consider as part of the 2021 Capital Budget, the construction of a concrete sidewalk, for students and pedestrians from ODSS high school, and which would connect to the walkway between Bredin Parkway and Northgate Drive. Currently there are no sidewalks in this area nor are there any sidewalks on Glenforest Road or Forest Park Road.

□ Option 1 – 1.8-metre-wide sidewalk on the north and west side of Sunset Drive from ODSS to Northgate as shown on the attached plan;

X Option 2 – no sidewalk. (Leave as is.)

Additional Comments: We are a Sunset Drive resident and strongly oppose.

Thank you for taking the time to complete this brief questionnaire and survey. Please return your survey by 4:00 P.M. on Wednesday March 24th, 2021.


Yours truly,


1. Durst

T. Dulisse, CET Engineering Technologist, Infrastructure Services, 87 Broadway

Enclosed - Falkner Street-Sunset Drive Sidewalk Location Plan

Report No. INS-2020-013 Falkner Street - Sunset Drive 1.8 metre Curb Face Proposed Sidewalk





From:	
То:	publicworksinfo
Subject:	Falkner Street-Sunset Drive Sidewalk Location Plan
Date:	Thursday, March 11, 2021 9:41:32 AM

I am emailing in response to the letter dropped off in my mailbox located at 3 Northgate Dr. We are choosing to check option 2. No sidewalk and leave as is.

If anything a light at the corners and catwalks would provide more safety than a sidewalk.

From:	
То:	publicworksinfo
Subject:	Proposed Sidewalk Sunset Drive Survey
Date:	Wednesday, March 10, 2021 12:36:23 PM

Thank you for this opportunity to make my views known.

I vote for Option 2 - no sidewalk - leave as is.

Best,

Jana Bell 23 Sunset Drive